



**BMAA Defect Alert #0045: BMAA SB 2462 - Inspection for material type
- Control Cable Shackles & Elevator Joiner**

Dated: 17/01/2014

The Service Bulletin below is now the subject of a CAA EMPD: 2014-001E

Here is a direct link:

<http://www.caa.co.uk/docs/33/20140117MPD2014001E.pdf>

BMAA Service Bulletin SB 2462:

Skyranger - Inspection for material type control cable shackles & elevator joiner

Live on the BMAA website: http://www.bmaa.org/files/2462_1_sb.pdf

This service bulletin has been raised to issue 2 to extend the inspection to all Sky Ranger series aircraft (Classic/Swift/– irrespective of when the aircraft or its parts were manufactured. This follows some reports that spares from affected batches may have been fitted to some older aircraft and not clearly recorded.

As detailed this SB must be carried out within the next 5 flight hours or by 31 January 2014, whichever comes first.

Please feel free to contact the Tech Office if you have any questions or if you find defective parts.

Kind regards,
Rob

Rob Mott
Chief Inspector
British Microlight Aircraft Association
01869 336005
[*robert@bmaa.org*](mailto:robert@bmaa.org)