



BMAA Defect Alert #0047: Light Sport Aircraft Ltd SB10 – Underwing fairing

Dated: 17/01/2014

Light Sport Aircraft Ltd has issued a Service Bulletin for all EV-97 Teameurostar aircraft.

SB10 – Underwing fairing

Link to website:

<http://www.lightsportaviation.org.uk/SB010%20Underwing%20fairing%20Issue%201.pdf>

Please see the SB for full details, to be carried out within the next 10 flying hours. A copy of the SB follows this defect note.

If the rivets are damaged and required replacement, it is essential the defect rectification instructions are followed. Owners/operators are encouraged to contact LSA Ltd and/or the BMAA Tech Office in such circumstances for assistance and guidance.

If you have any questions feel free to get in touch.

Kind regards,
Rob

Rob Mott
Chief Inspector
British Microlight Aircraft Association
01869 336005
[*robert@bmaa.org*](mailto:robert@bmaa.org)