



MANDATORY PERMIT DIRECTIVE

In accordance with Article 9A(5)(b) of the Air Navigation Order 2000 as amended, the following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

MPD: 2004-015 AERIAL ARTS / CYCLONE AIRSPORTS / PEGASUS AVIATION / COSMIK AVIATION

Subject: Understrength kingpost.

Applicability: Chaser S, Chaser S447, Chaser S508 and Chaser S1000 microlight aeroplanes.

Reason: It has been established that the kingpost on some microlight aeroplanes has been made from material of inadequate strength.

Compliance: Before further flight, inspect the kingpost in accordance with Cosmik Aviation Service Bulletin SB/CHA/004 Issue 1.

If fitted with a Type 1 or Type 2 kingpost, which is undamaged, the microlight aeroplane may be returned to service.

A damaged Type 1 or Type 2 kingpost must be assessed and replaced in accordance with SB/CHA/004 Issue 1.

A Type 3 kingpost must be replaced before further flight.

Copies of the Service Bulletin may be obtained from:

Cosmik Aviation Ltd
Burnside
Deppers Bridge
Southam
Warwickshire
CV47 2SU

Tel: 01926 614422
Fax: 01926 613781

Record compliance with this MPD in the aircraft log book.

This MPD becomes effective on 29 December 2004.